

FIG 1a

FLIP




FIG 1b

GRIND




FIG 1c

ETCH AND POLISH




FIG 1d




FIG 1e

LASER CUT




FIG 1f

28




FIG 1g




FIG 2a

FLIP
↓




FIG 2b




FIG 2c

↓




FIG 2d

SILICON BOND
↓




FIG 2e

ETCH
↓




FIG 2f

FLIP
↓




FIG 2g

SHEAR
↓




FIG 2h

ETCH AND POLISH
↓




FIG 3a




FIG 3b




FIG 3c




FIG 3d





FIG 3e





FIG 3f





FIG 3g




FIG 3h




FIG 3i




FIG 3j